



8820 Old Highway 99 SE, Olympia, Washington 98501, USA
360-943-6063 800-562-6184 800-445-0450 FAX 360-352-4813

**Product
Bulletin**

RISE-N-SHINE METAL CLEANER

APPLICATION

CH₂O's **RISE-N-SHINE** is a fast acting metal cleaner that strips away stains, soils, and metal deposits leaving a fresh clean surface. It is exceptional for removing hard water deposits and for cleaning iron, copper, aluminum and other alloy metals. **RISE-N-SHINE** is also an outstanding product for removing water spots from window glass.

DIRECTIONS FOR USE

RISE-N-SHINE may be used full strength or diluted to an appropriate strength with water. For best results, spray **RISE-N-SHINE** on the surface to be cleaned by any convenient method. Contact time will vary depending upon the severity of the area to be cleaned. Rinse with cool water. This will leave an oxide-free surface in a "like-new" condition.

For Glass: Never clean in the sun with **RISE-N-SHINE**. Wet down all surfaces to be cleaned and the drip zone with cold water. Apply **RISE-N-SHINE** with a damp sponge starting from the bottom and working up the glass. Scrub with a green scrub pad for 30 seconds to 1 minute before rinsing off the surface and squeegeeing dry. Repeat these steps as needed until all water spots or scale is gone. Never let **RISE-N-SHINE** dry on glass!

SAFETY & HANDLING PROCEDURE

This is an acidic product. Impervious gloves should be worn when handling, as prolonged or repeated exposure can cause irritation and/or burns. If a potential for eye exposure exists, safety glasses should also be worn. Read the Material Safety Data Sheet for additional handling and first aid directions.

PHYSICAL PROPERTIES

Appearance Yellow Liquid
Odor Moderate Licorice
pH of 1% Solution 1.0-3.0
Pounds per Gallon 9.7-10.2

December 22, 1997

